

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, January 14, 2022	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 14649+50 – 14720+00 MVP-FR-321/321.01	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-H40, S-H39, W-H17, S-H37, W-H16, S-H36, W-H14, SH35, S-H32 and W-H11.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Friday, January 14, 2022

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, January 14, 2022

Figure 1: STA 14720+00 – Controls in place and functioning properly.

BRG: 95°E (T) **LAT:** 36.988003 **LON:** -79.701744 ±16ft **ALT:** 934ft



Figure 2: STA 14690+00 – Controls in place and functioning properly.

BRG: 287°W (T) **LAT:** 36.989678 **LON:** -79.710499 ±2037ft **ALT:** 990ft



Figure 3: STA 14664+00 – Controls in place and functioning properly.

BRG: 298°NW (T) **LAT:** 36.989070 **LON:** -79.720912 ±32ft **ALT:** 982ft



Figure 4: STA 14653+00 – Controls in place and functioning properly.

BRG: 116°SE (T) **LAT:** 37.005188 **LON:** -79.720545 ±13723ft **ALT:** 996ft

