

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, January 13, 2022	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Franklin County	STA 13260+00 – 13316+00 MVP-FR-293.01	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-II4 and S-GH7.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Thursday, January 13, 2022

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, January 13, 2022

Figure 1: STA 13262+00 – Controls in place and functioning properly.
BRG: 320°NW (T) LAT: 37.115549 LON: -80.060545 ±32ft ALT: 1459ft



Figure 2: STA 13273+00 – Controls in place and functioning properly.
BRG: 294°NW (T) LAT: 37.115486 LON: -80.056203 ±32ft ALT: 1644ft



Figure 3: STA 13292+00 – Controls in place and functioning properly.
BRG: 160°S (T) LAT: 37.114868 LON: -80.056258 ±16420ft ALT: 1859ft



Figure 4: STA 13305+00 – Controls in place and functioning properly.
BRG: 104°E (T) LAT: 37.112817 LON: -80.058262 ±16420ft ALT: 1697ft

