

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, February 15, 2022	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Pittsylvania County	STA 15370+62 – 15496+70	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-G6, S-G5, S-G4, S-G3 and S-CC16.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Tuesday, February 15, 2022

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, February 15, 2022

Figure 1: STA 15375+00 – Controls in place and functioning properly.

BRG: 338°N (T) **LAT:** 36.906806 **LON:** -79.523203 ±18248ft **ALT:** 777ft



Figure 2: STA 15425+00 – Controls in place and functioning properly.

BRG: 82°E (T) **LAT:** 36.948414 **LON:** -79.474380 ±14940ft **ALT:** 765ft



Figure 3: STA 15457+00 – Controls in place and functioning properly.

BRG: 278°W (T) **LAT:** 36.912802 **LON:** -79.485058 ±16ft **ALT:** 825ft



Figure 4: STA 15496+00 – Controls in place and functioning properly.

BRG: 334°NW (T) **LAT:** 36.918046 **LON:** -79.482240 ±620ft **ALT:** 899ft

