

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, February 11, 2022	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Roanoke County	STA 12637+00 – 12600+00 MVP-RO-279.01/02	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: N/A

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Friday, February 11, 2022

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, February 11, 2022

Figure 1: STA 12634+00 – Controls in place and functioning properly.

BRG: 328°NW (T) **LAT:** 37.238062 **LON:** -80.168425 ±4701ft **ALT:** 3610ft



Figure 2: STA 12623+00 – Controls in place and functioning properly.

BRG: 150°SE (T) **LAT:** 37.194827 **LON:** -80.177779 ±98ft **ALT:** 3264ft



Figure 3: STA 12613+00 – Controls in place and functioning properly.

BRG: 352°N (T) **LAT:** 37.196949 **LON:** -80.179735 ±164ft **ALT:** 3301ft



Figure 4: STA 12606+00 – Controls in place and functioning properly.

BRG: 305°NW (T) **LAT:** 37.198275 **LON:** -80.181050 ±32ft **ALT:** 3213ft

