

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, February 8, 2022	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 14018+47 – 14131+28 MVP-FR-309	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-KL32, S-YZ5, S-YZ4, S-EF48, W-EF51, S-KL61 and S-KL41.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Tuesday, February 8, 2022

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, February 8, 2022

Figure 1: STA 14066+00 – Controls in place and functioning properly.

BRG: 90°E (T) **LAT:** 37.064753 **LON:** -79.875433 ±1755ft **ALT:** 1191ft



14066

Figure 2: STA 14073+00 – Controls in place and functioning properly.

BRG: 118°SE (T) **LAT:** 37.063975 **LON:** -79.872629 ±213ft **ALT:** 1189ft



14073

Figure 3: STA 14112+00 – Controls in place and functioning properly.

BRG: 82°E (T) **LAT:** 37.063472 **LON:** -79.860473 ±16ft **ALT:** 1092ft



14112

Figure 4: STA 14128+00 – Controls in place and functioning properly.

BRG: 292°W (T) **LAT:** 37.062775 **LON:** -79.853202 ±1617ft **ALT:** 1093ft



14128