

FIELD INSPECTION REPORT

| | | | |
|------------------------------|--------------------------|------------------|-----------------------------|
| Project Name: | Mountain Valley Pipeline | Inspector: | Marshall Willis |
| Inspection Date: | Thursday, March 10, 2022 | Project Contact: | Brian Clauto, Cory Chalmers |
| Spread I: Franklin County | STA 14333+27 – 14454+22 | Weather: | Wet |

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-A36, S-A38, S-A40, W-DD1, S-A41, S-GH36, S-KL17, S-GH37, S-GH39, S-GH40, S-GH44 and W-GH16.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Thursday, March 10, 2022

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, March 10, 2022

Figure 1: STA 14335+00 – Controls in place and functioning properly.

BRG: 164°S (T) **LAT:** 37.038008 **LON:** -79.807023 ±213ft **ALT:** 1201ft



14335

Figure 2: STA 14370+00 – Controls in place and functioning properly.

BRG: 128°SE (T) **LAT:** 37.066897 **LON:** -79.808225 ±15085ft **ALT:** 1110ft



14370

Figure 3: STA 14413+00 – Controls in place and functioning properly.

BRG: 88°E (T) **LAT:** 37.030975 **LON:** -79.781011 ±16ft **ALT:** 1049ft



14413

Figure 4: STA 14445+00 – Controls in place and functioning properly.

BRG: 256°W (T) **LAT:** 37.024778 **LON:** -79.771264 ±3631ft **ALT:** 1111ft



14445