

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, March 1, 2022	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12233+00 – 12285+00 MVP-MN-276.03	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: N/A

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Tuesday, March 1, 2022

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, March 1, 2022

Figure 1: STA 12281+00 – Controls in place and functioning properly.

BRG: 257°W (T) **LAT:** 37.252173 **LON:** -80.224259 ±7755ft **ALT:** 2779ft



Figure 2: STA 12268+00 – Controls in place and functioning properly.

BRG: 242°SW (T) **LAT:** 37.244631 **LON:** -80.201937 ±24924ft **ALT:** 2736ft



Figure 3: STA 12253+00 – Controls in place and functioning properly.

BRG: 221°SW (T) **LAT:** 37.237108 **LON:** -80.232284 ±675ft **ALT:** 1481ft



Figure 4: STA 12241+00 – Controls in place and functioning properly.

BRG: 74°E (T) **LAT:** 37.252383 **LON:** -80.243696 ±16ft **ALT:** 2380ft

