

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, April 7, 2022	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Pittsylvania County	STA 15142+66 – 15260+00 MVP-PI-326/328	Weather:	Rainy

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-F1, S-C7 and S-F2.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Thursday, April 7, 2022

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, April 7, 2022

Figure 1: STA 15146+00 – Controls in place and functioning properly.

BRG: 65°NE (T) LAT: 36.967640 LON: -79.587192 ±25810ft ALT: 845ft



15146

Figure 2: STA 15165+00 – Controls in place and functioning properly.

BRG: 126°SE (T) LAT: 36.944450 LON: -79.572400 ±22ft ALT: 718ft



15165

Figure 3: STA 15172+00 – Controls in place and functioning properly.

BRG: 300°NW (T) LAT: 36.943610 LON: -79.570585 ±19ft ALT: 806ft



15172

Figure 4: STA 15202+00 – Controls in place and functioning properly.

BRG: 111°E (T) LAT: 36.940188 LON: -79.561034 ±29ft ALT: 828ft



15202