

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, June 30, 2022	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Pittsylvania County	STA 16003+44– 16027+46 H-602/H-603 Line Transco Station	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| ☐ Tree Felling | ☐ Clearing/Grubbing | ☐ Grading | ☐ Trenching | ☐ Stringing/Welding |
| ☐ Lowering/Backfilling | ☐ Final Restoration | ☐ Temp. Stabilization | ☐ Perm. Stabilization | ☒ Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-EF26, S-H44 and S-H41.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Thursday, June 30, 2022

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, June 30, 2022

Figure 1: H-603 Line 18+00 – Controls in place and functioning properly.



Figure 2: H-602 Line 09+00 – Controls in place and functioning properly.



Figure 3: STA 16007+00 – Controls in place and functioning properly.



Figure 4: STA 16038+00 – Controls in place and functioning properly.

