

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Tuesday, October 4, 2022	Project Contact:	Brian Clauto
Spread H: Montgomery	ATWS 701, 703, 704A, 1446, 1375 AR MN 272, 271, 270.01, 274, 275 ST 12170-12200, 13111-12100	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Grading
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
☒ Dormant

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

- Comments: Inspected the following resources: S-F15, S-F16a/b, W-F9, S-MM11, W-KL6, W-C6, S-C21, S-0011
- ECD's were in place and functioning at the designated crossings.

Routine Maintenance: (*72-Hour Deadline from Notification*)

- N/A

Ineffective Controls: (*24-Hour Deadline from Notification*)

- N/A

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____  _____

Date: Tuesday, October 4, 2022

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, October 4, 2022

- Figure 1: Designated crossing S-C21, ECD's are in place.



- Figure 2: Designated crossing W-C6, ECD's are in place.



- Figure 3: Designated crossing S-MM11, ECD's are in place.



- Figure 4: St 12170, ECD's are in place and functioning.

