

## **FIELD INSPECTION REPORT**

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Tuesday, March 14, 2023	Project Contact:	Brian Clauto
Spread H: Franklin	Sta 13342-13415 ATWS 1352	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)												
	Tree Fellin	g		Clearing/Grubbing		Grading		Trenching		String	ging/Welding	
	☐ Lowering/Backfilling			Final Grading		Temp. Stabilization		Perm. Stabilization	$\boxtimes$	□ Dormant		
									Yes	No	N/A	
	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?						$\boxtimes$					
Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?							$\boxtimes$					
	3.	Areas of off	site s	sediment deposition o	bserve	d?				$\boxtimes$		
<ul> <li>Comments: Inspected the following resources: S-RR08, S-RR09, S-RR10, S-RR11, S-IJ1, S-IJ3, W-IJ1, W-IJ2</li> <li>ECD's were in place and functioning at the designated crossings.</li> <li>Routine Maintenance: (72-Hour Deadline from Notification)         <ul> <li>N/A</li> </ul> </li> <li>Ineffective Controls: (24-Hour Deadline from Notification)         <ul> <li>N/A</li> </ul> </li> <li>Recommended Corrective Action: N/A</li> </ul>												
Deadline: N/A  The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.  Inspector Signature:												
Date: Tuesday, March 14, 2023												

## FIELD INSPECTION PHOTO LOG



Project Name: Mountain Valley Pipeline Date: Tuesday, March 14, 2023

Figure 1: Designated crossing S-RR08, ESC in place.



Figure 2: Designated crossing S-RR11, ESC in place.



Figure 3: Sta 13403, ESC in place.



Figure 4: Designated crossing S-IJ1, ESC in place.

