

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, February 27, 2023	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 14861+31 – 14928+52	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☐ | ☒ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-SS8, S-CD8, S-AB8, S-DD3 and S-G16.

Routine Maintenance: (72-Hour Deadline from Notification)

- STA 14870+00: Clean up trash along ROW.
- STA 14882+00: Re-stabilize travel lane CIS stream S-CD8.
- STA 14888+00: Re-stabilize travel lane CIS stream S-AB8.
- STA 14905+00 to 14907+00: Re-stabilize travel lane.

Recommended Corrective Action: Maintain and install all controls per the approved PSS&S.

Deadline: Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: **Monday, February 27, 2023**

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, February 27, 2023

Figure 1: STA 14870+00 – Pick up trash along ROW.



Figure 2: STA 14882+00 – Restabilize travel lane CIS S-CD8.



Figure 3: STA 14890+00 – Re-stabilize travel lane CIS S-AB8.



Figure 4: STA 14905+00 to 14907+00 – Re-stabilize travel lane.

