

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Tuesday, March 21, 2023	Project Contact:	Brian Clauto
Spread H: Roanoke	Sta 12644-12600 ATWS 1329, 698, 1225, 1224 AR RO 279.01	Weather:	Dry

ACT	IVE STAGE	OF CONST	RUC	TION: (Check all th	at apply)					
☐ Tree Felling		☐ Clearing/Grubbing			☐ Grading		☐ Trenching		Strii	nging/Welding	
	Lowering/E	Backfilling		Final Grading		Temp. Stabilization		Perm. Stabilization	tion 🗵 Do		mant
									Yes	No	N/A
Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?							\boxtimes				
	2.	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?							\boxtimes		
	3.	Areas of of	fsite	sediment deposition	observe	d?				\boxtimes	
	Comments:	Inspected t	he fol	llowing resources: N	I/A						
Routine Maintenance: (<u>72-Hour Deadline</u> from Notification) - N/A											
Ineffective Controls: (<u>24-Hour Deadline</u> from Notification) - N/A											
Recommended Corrective Action: N/A											
Dea	dline: N//	<u>A</u>									_

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____

Date: Tuesday, March 21, 2023



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline <u>Date</u>: Tuesday, March 21, 2023







Figure 3: ATWS 1225, ESC in place.



Figure 4: Sta 12600, ESC in place.

