

## **FIELD INSPECTION REPORT**

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, March 28, 2023	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Roanoke County	STA 12724+00 - 12776+00 MVP-RO-281/281.01 MVP-RO-282	Weather:	Dry

		IVIVE	-NO-202									
ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)												
	Tree Felling		Clearing/Grubbing		Grading		Trenching		Stri	nging/Welding		
	Lowering/Backfillir	g 🗆	Final Restoration		Temp. Stabilization		Perm. Stabilization	Stabilization 🗵 Dormant				
								Yes	No	N/A		
Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?						$\boxtimes$						
Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?								$\boxtimes$				
	3. Areas	of offsite	sediment deposition o	bserve	d?				$\boxtimes$			
	Comments: Inspected the following resources: S-EF56 and S-EF32.  Routine Maintenance: ( <u>72-Hour Deadline from Notification</u> ) - STA 12731+00: SSF maintenance needed STA 12739+00: Re-stabilization needed.  Recommended Corrective Action: Maintain and install all controls per the approved PSS&S.											
	<u>Deadline:</u> Within 72-Hour of Notification											

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** 

Date: Tuesday, March 28, 2023



## FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

<u>Date</u>: Tuesday, March 28, 2023

