

## FIELD INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Monday, April 24, 2023	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread H: Montgomery County</b>	STA 12071+50 – 12190+85 MVP-MN-270 MVP-MN-274	<b>Weather:</b>	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Tree Felling

☐ Clearing/Grubbing

☐ Grading

☐ Trenching

☐ Stringing/Welding

☐ Lowering/Backfilling

☐ Final Restoration

☐ Temp. Stabilization

☐ Perm. Stabilization

☒ Dormant

- |    |   | Yes                                 | No                                  | N/A                      |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

**Comments:** Inspected the following resources: S-MM15, S-MM14, S-MM13, S-MM11, S-F15, W-F9-PFO, S-F16A/B, S-C36, W-C12, W-C11, W-C8, S-MM31, S-C29, W-C6, W-C5, S-C25 and S-C24.

**Recommended Corrective Action:** N/A

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** 

**Date:** Monday, April 24, 2023

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Monday, April 24, 2023

**Figure 1: STA 12092+00** – Controls in place and functioning properly.



**Figure 2: STA 12111+00** – Controls in place and functioning properly.



**Figure 3: STA 12141+00** – Controls in place and functioning properly.



**Figure 4: STA 12185+00** – Controls in place and functioning properly.

