

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, May 25, 2023	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 14250+00 – 14311+57 MVP-FR-313	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-F11, S-F9B, S-F9A and S-F10.

Routine Maintenance: (72-Hour Deadline from Notification)

- STA 14278+50: P1 maintenance needed. Cattle damage.
- STA 14294+00: P1 maintenance needed. Cattle damage.
- STA 14295+00: Restabilize stockpile.
- STA 14297+00: Restabilize stockpile.

Deadline: Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: **Thursday, May 25, 2023**

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, May 25, 2023

Figure 1: STA 14278+50 – P1 Maintenance. Cattle damage.



Figure 2: STA 14294+00 – P1 Maintenance. Cattle damage.



Figure 3: STA 14295+00 – Re-stabilize stockpile.



Figure 4: STA 14297+00 – Re-stabilize stockpile.

