

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, August 23, 2023	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 13784+35 – 13811+81 STA 14018+47 – 14035+28 STA 13678+71 – 13690+91 STA 14131+28 – 14141+62 MVP-FR-300 MVP-FR-309	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|--|--|--|---|---|
| <input type="checkbox"/> Tree Felling | <input type="checkbox"/> Clearing/Grubbing | <input type="checkbox"/> Grading | <input checked="" type="checkbox"/> Trenching | <input checked="" type="checkbox"/> Stringing/Welding |
| <input checked="" type="checkbox"/> Lowering/Backfilling | <input type="checkbox"/> Final Restoration | <input type="checkbox"/> Temp. Stabilization | <input type="checkbox"/> Perm. Stabilization | <input checked="" type="checkbox"/> Resource Crossing |

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-E29, S-D23, S-D22, S-D20, S-KL39 and S-C8.

Ineffective Controls: (24-Hour Deadline from Notification)

- STA 13800+00: Install proper secondary containment.

Routine Maintenance: (72-Hour Deadline from Notification)

- STA 13804+64: Prevent discharge down fill slope.

Deadline: Various - See Comments

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Wednesday, August 23, 2023

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, August 23, 2023

Figure 1: Stream S-D20 – Controls in place and functioning properly.



Figure 2: STA 13804+54 – Water bar flow path maintenance needed to prevent discharge down fill slope.



Figure 3: STA 13800+00 – install proper secondary containment.



Figure 4: Stream S-KL39 – Controls in place and functioning properly.

