

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, August 22, 2023	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Roanoke County Franklin County	STA 12601+11 – 12664+40 MVP-RO-279.01/.02 MVP-FR-289 STA 13022+00 – 13034+97	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|---|--|--|
| <input type="checkbox"/> Tree Felling | <input type="checkbox"/> Clearing/Grubbing | <input checked="" type="checkbox"/> Grading | <input type="checkbox"/> Trenching | <input type="checkbox"/> Stringing/Welding |
| <input type="checkbox"/> Lowering/Backfilling | <input type="checkbox"/> Final Restoration | <input checked="" type="checkbox"/> Temp. Stabilization | <input type="checkbox"/> Perm. Stabilization | <input type="checkbox"/> Resource Crossing |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-G24, S-G25 and W-ST2-PEM.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: Tuesday, August 22, 2023

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, August 22, 2023

Figure 1: STA 12608+00 – Controls in place and functioning properly.



Figure 2: STA 13026+00 – Controls in place and functioning properly.



Figure 3: STA 13026+00 – Controls in place and functioning properly.



Figure 4: STA 12602+00 – Controls in place and functioning properly. Installing slope drains and stabilizing with matting.

