

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, August 16, 2023	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 13748+30 – 13836+95 STA 14018+47 – 14035+28 STA 13678+71 – 13690+91	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|---|---|
| <input type="checkbox"/> Tree Felling | <input type="checkbox"/> Clearing/Grubbing | <input type="checkbox"/> Grading | <input checked="" type="checkbox"/> Trenching | <input checked="" type="checkbox"/> Stringing/Welding |
| <input type="checkbox"/> Lowering/Backfilling | <input type="checkbox"/> Final Restoration | <input type="checkbox"/> Temp. Stabilization | <input type="checkbox"/> Perm. Stabilization | <input checked="" type="checkbox"/> Resource Crossing |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-EF7, S-EF12, S-MM42, S-RR15 S-D23, S-D22, S-D20, S-KL39, S-E29 and S-E28.

Routine Maintenance: (72-Hour Deadline from Notification)
 - STA 13791+68: SSF maintenance needed.

Deadline: Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: Wednesday, August 16, 2023

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, August 16, 2023

Figure 1: STA 13790+000 – Controls in place and functioning properly.



Figure 2: STA 13791+68 – SSF maintenance needed.



Figure 3: STA 14033+00 – Controls in place and functioning properly.



Figure 4: STA 13683+00 – Controls in place and functioning properly.

