

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, September 14, 2023	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Pittsylvania County	STA 15296+00 – 15370+62 MVP-PI-332	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-C3, S-C4, S-H13 and W-H5.

Minimum Standard 1: (*7 Day Deadline from Notification*)

- STA 15296+00 to 15323+24: Stabilize dormant areas within 7 days per MS-1.
- STA 15333+22 to 15350+82: Stabilize dormant areas within 7 days per MS-1.
- STA 15350+82 to 15370+62: Stabilize dormant areas within 7 days per MS-1.

Routine Maintenance: (*72-Hour Deadline from Notification*)

- STA 15330+00: Stabilize fill slopes.
- STA 15330+00: WB exceeds 5% slope.

Deadline: Various - See Comments

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Thursday, September 14, 2023

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, September 14, 2023

Figure 1: STA 15296+00 to 15323+24 – Stabilize inactive areas per MS-1.



Figure 2: STA 15330+00 – WB exceeds 5% slope.



Figure 3: STA 15330+00 – Stabilize fill slopes.



Figure 4: STA 15333+22 to 15350+82 – Stabilize inactive areas per MS-1.



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, September 14, 2023

Figure 5: STA 15350+82 to 15370+62 – Stabilize inactive areas per MS-1.

