

## FIELD INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Matthew Grant
<b>Inspection Date:</b>	Monday, November 13, 2023	<b>Project Contact:</b>	Brian Clauto
<b>Spread G: Giles</b>	Sta 10882-10880, 10510, 10590-10600, 10760-10780 ATWS 1360, 1332, 1333, 610, 610A, 339A, 816, 1056 AR GI 238, 234	<b>Weather:</b>	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Tree Felling     
 ☐ Clearing/Grubbing     
 ☒ Grading     
 ☒ Trenching     
 ☒ Stringing/Welding  
☒ Lowering/Backfilling     
 ☐ Final Grading     
 ☐ Temp. Stabilization     
 ☐ Perm. Stabilization     
 ☒ Resource Crossing

- |  | Yes                                 | No                                  | N/A                      |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

▪ Comments: Inspected the following resources: S-A32, S-Q12, S-S5, S-G32, S-S4, S-Z9, S-Z7, S-G35

**Routine Maintenance:** (72-Hour Deadline from Notification)

- N/A


**Ineffective Controls:** (24-Hour Deadline from Notification)

- N/A

**Recommended Corrective Action:** N/A

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** \_\_\_\_\_  \_\_\_\_\_


**Date:** Monday, November 13, 2023

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Monday, November 13, 2023

- Figure 1: Designated crossing S-A32, ECD's are in place for active construction.



- Figure 2: Designated crossings S-Z9, ECD's are in place for active construction.



- Figure 3: Designated crossing SZ17 bore pit, ECD's are in place.



- Figure 4: Designated crossing S-S4 bore site prep, ECD's are in place.

