

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, December 8, 2023	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 14333+27 – 14350+00 STA 14450+00 – 14470+00 MVP-FR-313.01	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|---|---|---|--|
| <input type="checkbox"/> Tree Felling | <input type="checkbox"/> Clearing/Grubbing | <input checked="" type="checkbox"/> Grading | <input type="checkbox"/> Trenching | <input type="checkbox"/> Stringing/Welding |
| <input type="checkbox"/> Lowering/Backfilling | <input checked="" type="checkbox"/> Final Restoration | <input checked="" type="checkbox"/> Temp. Stabilization | <input checked="" type="checkbox"/> Perm. Stabilization | <input type="checkbox"/> Resource Crossing |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-A36.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Friday, December 8, 2023

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, December 8, 2023

Figure 1: STA 14335+00 – Controls installed and functioning properly.

☉ 157°SE (T) ☉ 37°2'19"N, 79°48'17"W ±39ft ▲ 1065ft



14335
08 Dec 2023

Figure 2: STA 14350+00 – Controls installed and functioning properly.

☉ 83°E (T) ☉ 37°2'12"N, 79°48'4"W ±13ft ▲ 1138ft



14350
08 Dec 2023

Figure 3: STA 14465+00 – Controls installed and functioning properly.

☉ 161°S (T) ☉ 37°1'29"N, 79°45'58"W ±13ft ▲ 1108ft



14465
08 Dec 2023

Figure 4: STA 14453+00 – Permanent stabilization occurring.

☉ 283°W (T) ☉ 37°1'36"N, 79°46'6"W ±13ft ▲ 1124ft



Webster
08 Dec 2023