

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, December 6, 2023	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Pittsylvania County	STA 15743+85 – 15772+27 MVP-PI-338/338.01 STA 15826+77 – 15883+00 MVP-PI-339	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|---|--|--|
| <input type="checkbox"/> Tree Felling | <input type="checkbox"/> Clearing/Grubbing | <input checked="" type="checkbox"/> Grading | <input type="checkbox"/> Trenching | <input type="checkbox"/> Stringing/Welding |
| <input type="checkbox"/> Lowering/Backfilling | <input type="checkbox"/> Final Restoration | <input checked="" type="checkbox"/> Temp. Stabilization | <input type="checkbox"/> Perm. Stabilization | <input type="checkbox"/> Resource Crossing |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-DD4, S-G2, W-G2 and S-B2.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Wednesday, December 6, 2023

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, December 6, 2023

Figure 1: STA 15751+00 – Controls installed and functioning properly.

☉ 95°E (T) ● 36°52'18"N, 79°24'25"W ±59ft ▲ 929ft



15751
06 Dec 2023

Figure 2: STA 15768+00 – Temporary stabilization application.

☉ 308°NW (T) ● 36°52'13"N, 79°24'7"W ±13ft ▲ 823ft



15768
06 Dec 2023

Figure 3: Stream S-B2 – Controls installed and functioning properly.

☉ 116°SE (T) ● 36°50'58"N, 79°22'40"W ±9ft ▲ 736ft



S-B2
06 Dec 2023

Figure 4: STA 15883+00 – Controls installed and functioning properly.

☉ 90°E (T) ● 36°50'55"N, 79°22'33"W ±19ft ▲ 743ft



15883
06 Dec 2023