

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, November 28, 2023	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Pittsylvania County Franklin County	STA 15370+62 – 15480+67 STA 14915+00 – 14928+52	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☒ Trenching
 ☒ Stringing/Welding
☒ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Resource Crossing

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-G6, S-G5, S-G4, S-G3, S-CC16 and S-G16.

Routine Maintenance: (72-Hour Deadline from Notification)

- STA 14920+00: Stabilize fill slope along travel lane.

Ineffective Controls: (24-Hour Deadline from Notification)

- STA 15384+00: Repair P1.

Deadline: Various - See Comments

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Tuesday, November 28, 2023

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, November 28, 2023

Figure 1: STA 14931+00 – Controls installed and functioning properly. Area temp. stabilized.

☉ 61°NE (T) ● 36°58'3"N, 79°38'14"W ±13ft ▲ 867ft



14931
28 Nov 2023

Figure 2: STA 14920+00 – Stabilize fill slopes on travel lane.

☉ 305°NW (T) ● 36°58'5"N, 79°38'25"W ±13ft ▲ 821ft



Stabilize fill slopes

14920
28 Nov 2023

Figure 3: STA 15384+00 – Repair p1 at CIS of S-G6.

☉ 262°W (T) ● 36°55'14"N, 79°30'20"W ±13ft ▲ 770ft



P1

S-G6
28 Nov 2023

Figure 4: Stream S-G5 – Controls installed and functioning properly.

☉ 223°SW (T) ● 36°55'3"N, 79°29'47"W ±9ft ▲ 820ft



S-G5
28 Nov 2023