

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, November 27, 2023	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Roanoke County Franklin County	STA 12855+00 – 12870+00 STA 13190+00 – 13197+00 STA 13411+00 – 13420+00 MVP-FR-292.01	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☒ Trenching
 ☒ Stringing/Welding
☒ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Resource Crossing

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: W-AB6, W-AB5, W-AB3, W-EF46, S-ST9b, S-D10, S-D8, S-IJ1, S-IJ2, W-IJ1 and W-IJ2.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: Monday, November 27, 2023

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, November 27, 2023

Figure 1: STA 12864+00 – Controls installed and functioning properly.

☉ 295°NW (T) ● 37°9'19"N, 80°7'45"W ±22ft ▲ 2649ft



12864
27 Nov 2023

Figure 2: STA 12858+00 – Controls installed and functioning properly.

☉ 283°W (T) ● 37°9'23"N, 80°7'51"W ±157ft ▲ 2613ft



12858
27 Nov 2023

Figure 3: Stream S-D8 – Controls installed and functioning properly.

☉ 30°NE (T) ● 37°7'22"N, 80°4'28"W ±13ft ▲ 1429ft



S-D8
27 Nov 2023

Figure 4: Stream S-IJ1 – Controls installed and functioning properly.

☉ 282°W (T) ● 37°5'34"N, 80°1'38"W ±26ft ▲ 1433ft



S-IJ1
27 Nov 2023