

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, December 20, 2023	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 14454+22 – 14524+76 MVP-FR-317	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☒ Final Restoration
 ☒ Temp. Stabilization
 ☒ Perm. Stabilization
 ☐ Resource Crossing

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-G22, S-G23, S-G21 and S-G20.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Wednesday, December 20, 2023

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, December 20, 2023

Figure 1: STA 14458+00 – Controls installed and functioning properly.

☉ 119°SE (T) ● 37.026226°N, 79.767730°W ±13ft ▲ 1123ft



Figure 2: STA 14465+00 – Controls installed and functioning properly.

☉ 129°SE (T) ● 37.024850°N, 79.766408°W ±13ft ▲ 1103ft



Figure 3: Stream S-G20 – Controls installed and functioning properly.

☉ 6°N (T) ● 37.017212°N, 79.759822°W ±22ft ▲ 916ft



Figure 4: STA 14524+00 – Controls installed and functioning properly.

☉ 323°NW (T) ● 37.011230°N, 79.754499°W ±9ft ▲ 1082ft

