

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Wednesday, January 3, 2024	Project Contact:	Brian Clauto
Spread I: Franklin	Sta 13437+65-13420 Sta 14720-14730 AR FR 293.02	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☒ Stringing/Welding
☒ Lowering/Backfilling
 ☐ Final Grading
 ☐ Temp. Stabilization
 ☒ Perm. Stabilization
 ☒ Resource Crossing

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

- Comments: Inspected the following resources: S-IJ4, W-A8, S-A15, S-A19, S-A20

Routine Maintenance: (72-Hour Deadline from Notification)

- Sta13437-13430 CFS Needs maintenance or to be remove in center of Row that are not in use.
- Sta 13428+87 rill erosion requires repair and re stabilization.

Ineffective Controls: (24-Hour Deadline from Notification)

- N/A

Recommended Corrective Action: Maintain and install all controls per the approved PSS&S.

Deadline: Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____  _____

Date: Wednesday, January 3, 2024

FIELD INSPECTION PHOTO LOG


Project Name: Mountain Valley Pipeline

Date: Wednesday, January 3, 2024

- Figure 1: Sta 13430 CFS requires repair or removal.



- Figure 2: Sta 13427+87 repair rill and re stabilize.



- Figure 3: Designated crossing S-F11, ECD's are in place.



- Figure 4: Designated crossing S-IJ4, ECD's are in place.

