

## FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, January 11, 2024	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 13850+00 – 13875+16 MVP-FR-303.01	Weather:	Wet

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding  
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- |    |   | Yes                                 | No                                  | N/A                      |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-C17, W-CD6 and S-CD6.

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:**



**Date:** Thursday, January 11, 2024

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Thursday, January 11, 2024

**Figure 1: STA 13851+00** – Controls installed and functioning properly.

☉ 5°N (T) ☉ 37.059119°N, 79.920742°W ±95ft ▲ 1177ft



11 Jan 2024

**Figure 2: STA 13860+00** – Controls installed and functioning properly.

☉ 327°NW (T) ☉ 37.054591°N, 79.927756°W ±11925ft ▲ 1122ft



11 Jan 2024

**Figure 3: Stream S-C17** – Controls installed and functioning properly.

☉ 117°SE (T) ☉ 37.058456°N, 79.918166°W ±13ft ▲ 1036ft



S-C17  
11 Jan 2024

**Figure 4: Stream S-CD6** – Controls installed and functioning properly.

☉ 93°E (T) ☉ 37.057578°N, 79.914067°W ±13ft ▲ 1020ft



S-CD6  
11 Jan 2024