

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, January 9, 2024	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	MVP-FR-321 MVP-FR-321.01	Weather:	Rainy

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Tuesday, January 9, 2024

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, January 9, 2024

Figure 1: Tobacco Road Crossing – Controls installed and functioning properly.

☉ 344°N (T) ● 37.005460°N, 79.752674°W ±13ft ▲ 945ft



Tobacco
09 Jan 2024

Figure 2: Simmons Creek Road Crossing – Controls installed and functioning properly.

☉ 145°SE (T) ● 36.997670°N, 79.738529°W ±9ft ▲ 931ft



Simmons Creek
09 Jan 2024

Figure 3: Hwy 40 Crossing – Controls installed and functioning properly.

☉ 266°W (T) ● 36.990450°N, 79.724071°W ±13ft ▲ 985ft



40
09 Jan 2024

Figure 4: Jacks Creek Road Crossing – Controls installed and functioning properly.

☉ 104°E (T) ● 36.988239°N, 79.710405°W ±13ft ▲ 895ft



Jacks creek
09 Jan 2024