

COMPLAINT INVESTIGATION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Tuesday, February 13, 2024	Project Contact:	Brian Clauto
Spread G: Giles	215 & 217 Zells Mill Rd, Newport VA	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling ☐ Clearing/Grubbing ☐ Grading ☐ Trenching ☐ Stringing/Welding
☐ Lowering/Backfilling ☐ Final Restoration ☐ Temp. Stabilization ☐ Perm. Stabilization ☒ Other

- | | | Yes | No | N/A |
|----|---|-------------------------------------|--------------------------|-------------------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

Background: This investigation was conducted in response to the PREP complaint #312626 for the Quinn residence. The complaint described sediment in spring fed drinking water.

Observations:


1. DEQ inspectors inspected the ROW between MVP ROW stations 11255+77-11254+04. All ESC's were in place and functioning.
2. DEQ inspectors inspected the impacted area off site near the intersection of 42 and Clover Hollow Rd, crews were on site continuing sediment cleanup and ESC removal per PREP #312517.
3. DEQ inspectors along with Mr. Quinn observed clear water entering the spring screen box and exiting the spring house.

Comments: DEQ inspectors Matthew Grant and Marshall Willis met with Mr. Quinn at 215 Zells Mill Rd in Newport VA which is approximately 1.2 miles from the MVP pipeline ROW Blue Grass Trail Road crossing. Mr. Quinn stated his well water was his drinking source and no discoloration had occurred, only that the spring well house water had been discolored during rain events and was the source of water at the barn location.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____  _____

Date: Tuesday, February 13, 2024

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, February 13, 2024

Figure 1: Area near the intersection of 42 and Clover Hollow Rd.



Figure 2: Quinn property spring box.




Figure 3: Quinn property prescreen spring box.



Figure 4: Quinn property spring box outfall channel.

