

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, January 30, 2024	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Roanoke County	MVP-RO-283 STA 12790+00 – 12813+00	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Resource Crossing

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-IJ82, W-IJ94, S-IJ83, W-IJ95, S-IJ88, S-IJ89 and S-IJ90.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Tuesday, January 30, 2024

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, January 30, 2024

Figure 1: STA 12806+00 – Controls in place and functioning properly.

☉ 109°E (T) ☉ 37.167263°N, 80.138890°W ±42ft ▲ 2712ft



Figure 2: STA 12805+00 – Controls in place and functioning properly.

☉ 59°NE (T) ☉ 37.167673°N, 80.138680°W ±13ft ▲ 2682ft



Figure 3: Stream I-IJ88 – Controls in place and functioning properly.

☉ 52°NE (T) ☉ 37.168414°N, 80.138321°W ±9ft ▲ 2698ft



Figure 4: Stream I-IJ90 – Controls in place and functioning properly.

☉ 134°SE (T) ☉ 37.165723°N, 80.139343°W ±16ft ▲ 2701ft

