

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, February 28, 2024	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 13644+82 – 13748+30	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-GH3, S-GH2, S-E28(2), W-E7, W-E8, S-E28(3) and S-EF4.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Wednesday, February 28, 2024

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, February 28, 2024

Figure 1: STA 13665+00 – Controls in place and functioning properly.

☉ 106°E (T) ● 37.090437°N, 79.954470°W ±52ft ▲ 1233ft



28 Feb 2024

Figure 2: STA 13704+00 – Controls in place and functioning properly.

☉ 105°E (T) ● 37.082910°N, 79.945783°W ±13ft ▲ 1136ft



13704
28 Feb 2024

Figure 3: STA 13717+00 – Controls in place and functioning properly.

☉ 158°(null) (T) ● 37.082032°N, 79.942086°W ±39ft ▲ 1210ft



13717
28 Feb 2024

Figure 4: STA 13727+00 – Controls in place and functioning properly.

☉ 145°SE (T) ● 37.078594°N, 79.943322°W ±196ft ▲ 1177ft



13727
28 Feb 2024