

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, March 14, 2024	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12119+17 – 12190+85 MVP-MN-272 MVP-MN-273	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| ☐ Tree Felling | ☐ Clearing/Grubbing | ☐ Grading | ☐ Trenching | ☐ Stringing/Welding |
| ☐ Lowering/Backfilling | ☐ Final Restoration | ☐ Temp. Stabilization | ☐ Perm. Stabilization | ☒ Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-C36, W-C12, W-C8, S-C29, W-C6, W-C5, S-C25 and S-C24.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Thursday, March 14, 2024

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, March 14, 2024

Figure 1: STA 12153+00 – Controls in place and functioning properly.

☉ 105°E (T) ● 37.254897°N, 80.271161°W ±13ft ▲ 1535ft



Figure 2: STA 12183+00 – Controls in place and functioning properly.

☉ 104°E (T) ● 37.252919°N, 80.257705°W ±285ft ▲ 1312ft



Figure 3: STA 12121+00 – Controls in place and functioning properly.

☉ 96°E (T) ● 37.257297°N, 80.282040°W ±13ft ▲ 1420ft



Figure 4: STA 12136+00 – Controls in place and functioning properly.

☉ 293°NW (T) ● 37.256140°N, 80.276965°W ±19ft ▲ 1452ft

