

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, March 20, 2024	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Franklin County	STA 13342+67 – 13415+51	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-RR08, S-RR09, S-RR11, S-IJ1, S-IJ2, S-IJ3, W-IJ1 and W-IJ2.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Wednesday, March 20, 2024

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, March 20, 2024

Figure 1: Stream S-IJ1 – Controls in place and functioning properly.

☉ 328°NW (T) ● 37.092962°N, 80.027729°W ±29ft ▲ 1453ft



S-IJ1
20 Mar 2024

Figure 2: STA 13410+00 – Controls in place and functioning properly.

☉ 290°W (T) ● 37.093286°N, 80.028748°W ±13ft ▲ 1549ft



13410
20 Mar 2024

Figure 3: STA 13378+00 – Controls in place and functioning properly.

☉ 147°SE (T) ● 37.100454°N, 80.034640°W ±29ft ▲ 1757ft



13378
20 Mar 2024

Figure 4: STA 13358+00 – Controls in place and functioning properly.

☉ 311°NW (T) ● 37.101632°N, 80.040156°W ±16ft ▲ 1519ft



13358
20 Mar 2024