

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, March 21, 2024	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 14546+75 – 14649+67 MVP-FR-319.01	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-E18, S-E17 and S-E14.

Routine Maintenance: (*72-Hour Deadline from Notification*)

- STA 14548+00 to 14550+00: Repair rills and restabilize denuded areas.
- STA 14567+00 to 14568+00: Repair rills and restabilize denuded areas.
- STA 14568+50 to 14569+50: Repair rills and restabilize denuded areas.
- STA 14610+00 to 14612+00: Repair rills and restabilize denuded areas.
- STA 14614+00 to 14616+00: Repair rills and restabilize denuded areas.

Deadline: Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____



Date: **Thursday, March 21, 2024**

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, March 21, 2024

Figure 1: STA 14548+00 to 14550+00 – Repair rilling and restabilize denuded areas.

☉ 329°NW (T) ☉ 37.004755°N, 79.752197°W ±13ft ▲ 939ft



Restabilize repair till 72

14548 to 50
21 Mar 2024

Figure 2: STA 14567+00 to 14568+00 – Repair rilling and restabilize denuded areas.

☉ 233°SW (T) ☉ 37.001229°N, 79.747906°W ±9ft ▲ 883ft



Restabilize and repair rills 72

14567 to 68
21 Mar 2024

Figure 3: STA 14568+50 to 14569+50 – Repair rilling and restabilize denuded areas.

☉ 261°W (T) ☉ 37.001065°N, 79.746922°W ±13ft ▲ 880ft



Restabilize and repair rills 72

14568+50 - 14569+50
21 Mar 2024

Figure 4: STA 14610+00 to 14612+00 – Repair rilling and restabilize denuded areas.

☉ 270°W (T) ☉ 36.995902°N, 79.735297°W ±13ft ▲ 864ft



Restabilize repair rills 72

14610 to 14612
21 Mar 2024

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, March 21, 2024

Figure 5: STA 14614+00 to 14616+00 – Repair rilling and restabilize denuded areas.

☉ 334°NW (T) ● 36.995231°N, 79.734092°W ±16ft ▲ 920ft

