

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, April 25, 2024	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Pittsylvania County	STA 15296+00 – 15356+44 MVP-PI-332	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☒ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☐ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-C4, S-C3, S-H13 and W-H5.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Thursday, April 25, 2024

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, April 25, 2024

Figure 1: STA 15350+00 – Controls in place and functioning properly.

☉ 15°N (T) ● 36.924557°N, 79.516429°W ±13ft ▲ 741ft



15350
25 Apr 2024

Figure 2: Stream S-H13 – Controls in place and functioning properly.

☉ 169°S (T) ● 36.925162°N, 79.517354°W ±13ft ▲ 703ft



S-H13
25 Apr 2024

Figure 3: STA 15339+00 – Controls in place and functioning properly.

☉ 304°NW (T) ● 36.926080°N, 79.518924°W ±13ft ▲ 778ft



25 Apr 2024

Figure 4: STA 15302+00 – Controls in place and functioning properly.

☉ 163°S (T) ● 36.931561°N, 79.529479°W ±13ft ▲ 759ft



15302
25 Apr 2024