

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, April 24, 2024	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 13958+31 – 14010+05 MVP-FR-306.02	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☒ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☐ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-EF48, S-KL35, S-KL37 and S-KL38.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Wednesday, April 24, 2024

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, April 24, 2024

Figure 1: STA 13998+00 – Controls in place and functioning properly.

☉ 88°E (T) ● 37.051739°N, 79.887199°W ±16ft ▲ 1056ft



13998
24 Apr 2024

Figure 2: Stream S-KL36 – Controls in place and functioning properly.

☉ 331°NW (T) ● 37.053392°N, 79.884500°W ±13ft ▲ 1002ft



S-KL36
24 Apr 2024

Figure 3: STA 14001+00 – Controls in place and functioning properly.

☉ 171°S (T) ● 37.054138°N, 79.884164°W ±19ft ▲ 1064ft



14001
24 Apr 2024

Figure 4: STA 14006+00 – Controls in place and functioning properly.

☉ 64°NE (T) ● 37.055587°N, 79.884219°W ±39ft ▲ 1075ft



14006
24 Apr 2024