

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, April 23, 2024	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Roanoke County	STA 12866+36 – 12915+25 MVP-RO-286	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-IJ12, W-MN7, W-KL51, S-KL55, W-KL49, W-KL48, W-EF46 and S-ST9B.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Tuesday, April 23, 2024

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, April 23, 2024

Figure 1: STA 12915+00 – Controls in place and functioning properly.

☉ 47°NE (T) ● 37.139513°N, 80.130483°W ±29770ft ▲ 1098ft



Figure 2: STA 12902+00 – Controls in place and functioning properly.

☉ 40°NE (T) ● 37.146922°N, 80.134794°W ±98ft ▲ 2829ft



Figure 3: STA 12889+00 – Controls in place and functioning properly.

☉ 61°NE (T) ● 37.149943°N, 80.132736°W ±26ft ▲ 2619ft



Figure 4: STA 12870+00 – Controls in place and functioning properly.

☉ 42°NE (T) ● 37.154383°N, 80.129167°W ±16ft ▲ 2652ft

