

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, April 17, 2024	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Roanoke County	STA 12780+00 – 12810+00 MVP-RO-283	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☒ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☐ Dormant

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-IJ88, S-IJ82, W-IJ83, W-IJ95 and W-IJ84.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: **Wednesday, April 17, 2024**

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, April 17, 2024

Figure 1: STA 12797+00 – Controls in place and functioning properly.

☉ 195°S (T) ● 37.169569°N, 80.138101°W ±9ft ▲ 2716ft



Figure 2: Stream S-IJ88 – Controls in place and functioning properly.

☉ 262°W (T) ● 37.168449°N, 80.138372°W ±29ft ▲ 2693ft



Figure 3: Wetland W-IJ95 – Controls in place and functioning properly.

☉ 277°W (T) ● 37.169128°N, 80.138128°W ±22ft ▲ 2665ft



Figure 4: STA 12806+00 – Controls in place and functioning properly.

☉ 25°NE (T) ● 37.167433°N, 80.138674°W ±13ft ▲ 2688ft

