

## FIELD INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Monday, April 15, 2024	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread H: Franklin County</b>	STA 13316+13 – 13342+67	<b>Weather:</b>	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- |   |  |  |  |   |
|---|--|--|--|---|
| <input type="checkbox"/> Tree Felling         | <input type="checkbox"/> Clearing/Grubbing | <input type="checkbox"/> Grading             | <input type="checkbox"/> Trenching           | <input type="checkbox"/> Stringing/Welding  |
| <input type="checkbox"/> Lowering/Backfilling | <input type="checkbox"/> Final Restoration | <input type="checkbox"/> Temp. Stabilization | <input type="checkbox"/> Perm. Stabilization | <input checked="" type="checkbox"/> Dormant |

- |  | Yes                                 | No                                  | N/A                      |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-GH9, S-GH11, S-GH14 and S-GH15.

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** 

**Date:** Monday, April 15, 2024

# FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Monday, April 15, 2024

**Figure 1: STA 13342+00** – Controls in place and functioning properly.

☉ 341°N (T) ● 37.103930°N, 80.043623°W ±13ft ▲ 1547ft



13342  
15 Apr 2024

**Figure 2: STA 13335+00** – Controls in place and functioning properly.

☉ 266°W (T) ● 37.104780°N, 80.046011°W ±62ft ▲ 1455ft



13335  
15 Apr 2024

**Figure 3: STA 13326+00** – Controls in place and functioning properly.

☉ 280°W (T) ● 37.105620°N, 80.048537°W ±101ft ▲ 1462ft



13326  
15 Apr 2024

**Figure 4: STA 13318+00** – Controls in place and functioning properly.

☉ 306°NW (T) ● 37.106098°N, 80.051002°W ±36ft ▲ 1450ft



13318  
15 Apr 2024