

FIELD INSPECTION REPORT

| Project Name: | Mountain Valley Pipeline | Inspector: | Marshall Willis |
|-----------------------------|---------------------------------------|------------------|-----------------------------|
| Inspection Date: | Thursday, May 2, 2024 | Project Contact: | Brian Clauto, Cory Chalmers |
| Spread H: Roanoke County | STA 12915+20 - 12938+19 MVP-RO-286 | Weather: | Dry |

| | ACTIV | VE STAGE | OF C | CONSTRUCTION: (Ch | ieck all | that apply) | | | | | |
|--|---|------------------|-------------|-------------------------|----------|---------------------|-------------|---------------------|-----|-------------|---------------|
| | Tree Felling | | | Clearing/Grubbing | | Grading | | Trenching | | Strii | nging/Welding |
| | Lowering/B | Backfilling | \boxtimes | Final Restoration | | Temp. Stabilization | \boxtimes | Perm. Stabilization | | Dor | mant |
| | | | | | | | | | Yes | No | N/A |
| | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | | | | | | | \boxtimes | | | |
| | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | | | | | | | \boxtimes | | | |
| | 3. | Areas of o | ffsite | sediment deposition o | bserve | d? | | | | \boxtimes | |
| | <u>Com</u> | nments: Ins | specte | ed the following resour | ces: S | -EF44 and W-EF44. | | | | | |
| | | | | | | | | | | | |
| | | Hima. NI/ | ^ | | | | | | | | |
| | Dead | <u>lline:</u> N/ | <u>A</u> | | | | | | | | |
| The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project. | | | | | | | | | | | |
| | Inspe | ector Sigr | natur | e: Marshau | I K | Pillij . | | | | | |
| | Date | : Thurs | day, | May 2, 2024 | | | | | | | |



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, May 2, 2024





<u>Figure 3</u>: **Stream S-EF44** – Controls in place and functioning properly.



Figure 4: STA 12928+00 – Controls in place and functioning properly.

② 221°SW (T) ③ 37.142122°N, 80.138456°W ±36ft ▲ 2761ft

