

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, April 30, 2024	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Pittsylvania County	STA 15370+62 – 15480+67	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|---|--|--|--|
| <input type="checkbox"/> Tree Felling | <input type="checkbox"/> Clearing/Grubbing | <input type="checkbox"/> Grading | <input type="checkbox"/> Trenching | <input type="checkbox"/> Stringing/Welding |
| <input type="checkbox"/> Lowering/Backfilling | <input checked="" type="checkbox"/> Final Restoration | <input type="checkbox"/> Temp. Stabilization | <input type="checkbox"/> Perm. Stabilization | <input type="checkbox"/> Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-G6, S-G5, S-G4, S-G3 and S-CC16.

Ineffective Controls: (24-Hour Deadline from Notification)

- STA 15435+00: Sediment discharged off ROW. Retrieve sediment and stabilize.
- STA 15370+00: No RCE installed at Snowberry Rd. per the approved ECS plans.

Deadline: Within 24-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Tuesday, April 30, 2024

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, April 30, 2024

Figure 1: STA 15370+00 – RCE not installed at Snowberry Road approaches.

☉ 107°E (T) ● 36.922259°N, 79.510843°W ±13ft ▲ 787ft



No RCEs along Snowberry Rd 24hr

15370
30 Apr 2024

Figure 2: STA 15435+00 – Sediment discharged off ROW.

☉ 135°SE (T) ● 36.915750°N, 79.490275°W ±36ft ▲ 798ft



S
30 Apr 2024

Figure 3: STA 15435+00 – Sediment discharged off ROW.

☉ 174°S (T) ● 36.915737°N, 79.490245°W ±9ft ▲ 807ft



S
30 Apr 2024

Figure 4: Stream S-G4 – Controls in place and functioning properly.

☉ 137°SE (T) ● 36.916549°N, 79.492747°W ±9ft ▲ 781ft



S-G4
30 Apr 2024