

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Wednesday, June 26, 2024	Project Contact:	Brian Clauto
Spread I: Franklin	Sta 14760-14840 ATWS 373, 1389, 715, 375, 539	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☒ Final Grading
 ☐ Temp. Stabilization
 ☒ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

▪ **Comments:** Inspected the following resources: S-MM44, S-MM48, S-H25, S-H23, S-H24, S-H1, S-A13

Routine Maintenance: *(72-Hour Deadline from Notification)*

- Sta14768+50, denuded area requires re-stabilization.


Ineffective Controls: *(24-Hour Deadline from Notification)*

- N/A

Recommended Corrective Action: Maintain and install all controls per the approved PSS&S.

Deadline: Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____  _____

Date: **Wednesday, June 26, 2024**

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, June 26, 2024

Figure 1: Sta 14768+50, denuded area requires re-stabilization.



Figure 2: Designated crossing S-H23, final grading and controls are going in.



Figure 3: Sta 14791, ESC is in place for active construction.



Figure 4: Designated crossing S-MM44, ESC is in place.

