

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, June 26, 2024	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 14758+16 – 14845+68 MVP-FR-322 MVP-FR-323	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|---|--|---|---|
| ☐ Tree Felling | ☐ Clearing/Grubbing | ☐ Grading | ☐ Trenching | ☐ Stringing/Welding |
| ☐ Lowering/Backfilling | ☒ Final Restoration | ☐ Temp. Stabilization | ☒ Perm. Stabilization | ☒ Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-MM44, S-MM45, S-H25, W-H9, S-H24, S-H23, S-HH1, S-A13 and S-A11.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Wednesday, June 26, 2024

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, June 26, 2024

Figure 1: STA 14760+00 – Controls in place and functioning properly.

☉ 337°NW (T) ● 36.983358°N, 79.689685°W ±29ft ▲ 965ft



14760
26 Jun 2024

Figure 2: STA 14764+00 – Controls in place and functioning properly.

☉ 118°SE (T) ● 36.982727°N, 79.688359°W ±49ft ▲ 946ft



14764
26 Jun 2024

Figure 3: STA 14791+00 – Controls in place and functioning properly.

☉ 129°SE (T) ● 36.978568°N, 79.682877°W ±95ft ▲ 945ft



14791
26 Jun 2024

Figure 4: STA 14804+00 – Controls in place and functioning properly.

☉ 154°SE (T) ● 36.976571°N, 79.677690°W ±9ft ▲ 927ft



14804
26 Jun 2024