

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, June 17, 2024	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 14649+67 – 14694+77 MVP-FR-320	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☒ Perm. Stabilization
 ☐ Other

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-H40, W-H17, S-H37, S-H36, W-H16, W-H5, S-H36, W-H14 and S-H34.

Routine Maintenance: (72-Hour Deadline from Notification)

- STA 14694+50: Culverts along Jacks Creek Road need OP.

Deadline: Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Monday, June 17, 2024

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, June 17, 2024

Figure 1: Jacks Creek Rd. – SW culverts need OP.

☉ 237°SW (T) ● 36.988256°N, 79.710283°W ±13ft ▲ 941ft



Figure 2: STA 14657+00 – Controls in place and functioning properly.

☉ 306°NW (T) ● 36.989364°N, 79.722415°W ±13ft ▲ 927ft



Figure 3: STA 14663+00 – Controls in place and functioning properly.

☉ 268°W (T) ● 36.988906°N, 79.719959°W ±85ft ▲ 1010ft



Figure 4: STA 14679+00 – Controls in place and functioning properly.

☉ 97°E (T) ● 36.987996°N, 79.715362°W ±9ft ▲ 951ft

