

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, June 28, 2024	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Franklin County	STA 13115+97 – 13141+64 STA 13197+55 – 13218+53 MVP-FR-292 MVP-FR-291	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|---|--|---|---|
| ☐ Tree Felling | ☐ Clearing/Grubbing | ☐ Grading | ☐ Trenching | ☐ Stringing/Welding |
| ☐ Lowering/Backfilling | ☒ Final Restoration | ☐ Temp. Stabilization | ☒ Perm. Stabilization | ☒ Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-D17 and S-D14.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Friday, June 28, 2024

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, June 28, 2024

Figure 1: STA 13142+00 – Controls in place and functioning properly.

☉ 282°W (T) ☉ 17 N 581161 4108700 ±134ft ▲ 1437ft



13142
28 Jun 2024

Figure 2: STA 13132+00 – Controls in place and functioning properly.

☉ 91°E (T) ☉ 17 N 580771 4108770 ±13ft ▲ 1931ft



13132
28 Jun 2024

Figure 3: STA 13202+00 – Controls in place and functioning properly.

☉ 107°E (T) ☉ 17 N 582372 4108917 ±22ft ▲ 1690ft



13202
28 Jun 2024

Figure 4: STA 13202+00 – Controls in place and functioning properly.

☉ 242°SW (T) ☉ 17 N 582368 4108927 ±13ft ▲ 1636ft



13202
28 Jun 2024