

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, June 14, 2024	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12235+00 – 12217+00 STA 12445+19 – 12482+67 MVP-MN-276.03 MVP-MLV-AR-28	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|---|--|---|---|
| <input type="checkbox"/> Tree Felling | <input type="checkbox"/> Clearing/Grubbing | <input type="checkbox"/> Grading | <input type="checkbox"/> Trenching | <input type="checkbox"/> Stringing/Welding |
| <input type="checkbox"/> Lowering/Backfilling | <input checked="" type="checkbox"/> Final Restoration | <input type="checkbox"/> Temp. Stabilization | <input checked="" type="checkbox"/> Perm. Stabilization | <input checked="" type="checkbox"/> Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-CD12b and W-KL58.

Ineffective Controls: (24-Hour Deadline from Notification)

- STA 12470+00: Cleanup, properly dispose of or store fertilizer per Annual Specs/P2 Plan.

Deadline: Within 24-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Friday, June 14, 2024

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, June 14, 2024

Figure 1: STA 12470+00 – Cleanup, properly dispose of or store fertilizer per Annual Specs/P2 Plan.

☉ 188°S (T) ☉ 37.228714°N, 80.203970°W ±9ft ▲ 1251ft



Figure 2: STA 12225+00 – Controls in place and functioning properly.

☉ 100°E (T) ☉ 37.251892°N, 80.249128°W ±68ft ▲ 1940ft



Figure 3: MLV 28 – Controls in place and functioning properly.

☉ 7°N (T) ☉ 37.223761°N, 80.201898°W ±118ft ▲ 1787ft



Figure 4: STA 12477+00 – Controls in place and functioning properly.

☉ 165°S (T) ☉ 37.230324°N, 80.205512°W ±387ft ▲ 1410ft

