

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, July 17, 2024	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 13415+51 – 13425+00 MVP-FR-293.02 STA 13540+00 – 13543+00 STA 13889+00 – 13893+00	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☒ Perm. Stabilization
 ☐ Other

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-IJ4 and S-II9.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Wednesday, July 17, 2024

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, July 17, 2024

Figure 1: STA 13418+00 – Controls in place and functioning properly.

☉ 301°NW (T) LAT: 37.092209 LON: -80.026516 ±22ft ▲ 1466ft



13418
17 Jul 2024

Figure 2: MVP-FR-293.02 – Controls in place and functioning properly.

☉ 9°N (T) LAT: 37.090583 LON: -80.020274 ±13ft ▲ 1726ft



293.02
17 Jul 2024

Figure 3: STA 13542+00 – Controls in place and functioning properly.

☉ 110°E (T) LAT: 37.091388 LON: -79.990935 ±13ft ▲ 1301ft



House rock
17 Jul 2024

Figure 4: STA 13893+00 – Controls in place and functioning properly.

☉ 327°NW (T) LAT: 37.054889 LON: -79.910402 ±13ft ▲ 1113ft



Iron ridge
17 Jul 2024