



STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

Project Name:	Mountain Valley Pipeline	S&S Program:	Mountain Valley Pipeline (SS027)
Inspector:	Matthew Grant	Inspection Date:	Wednesday, July 31, 2024
Project Contact:	Cory Chalmers Brian Clauto	Project Contact Email:	cchalmers@equitransmidstream.com bclauto@equitransmidstream.com
Spread I: Franklin County	STA 14270- STA 14350 ATWS 525, 354, 353, 1485	Site Conditions:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling ☐ Clearing/Grubbing ☐ Rough Grading ☐ Trenching ☐ Stringing/Welding
- ☐ Lowering/Backfilling ☐ Final Grading ☐ Temp. Stabilization ☐ Perm. Stabilization ☒ Dormant

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-F9b, S-F10, S-F9a, S-GG4, S-A36

Routine Maintenance: (72-Hour Deadline from Notification)

- STA 14334- 14335 re stabilize denuded area.

Ineffective Controls: (24-Hour Deadline from Notification)

- N/A

Corrective Action: Maintain and install all controls per the approved S&S.

Deadline: Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:

STANDARDS & SPECIFICATIONS

SITE INSPECTION REPORT

LEVEL 1 (FIELD REPORT)

FIELD INSPECTION PHOTO LOG

Fig. 1

Description: Designated Crossing S-F9b, ECD's are in place.




Fig. 2

Description: Designated Crossing S-F10, ECD's are in place.



Fig. 3

Description: Designated crossing S-GG4, ECD's are in place.



Fig. 4

Description: STA 14334- 14335, denuded areas require re-stabilization.

