

STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT

LEVEL 1 (FIELD REPORT)

Project Name:	Mountain Valley Pipeline	S&S Program:	Mountain Valley Pipeline (SS027)
Inspector:	Marshall Willis	Inspection Date:	Thursday, September 12, 2024
Project Contact:	Cory Chalmers Brian Clauto	Project Contact Email:	cchalmers@equitransmidstream.com bclauto@equitransmidstream.com
Spread I: Franklin County	STA 13892+45 - STA 13958+31 STA 14644+69 - STA 14649+67 MVP-FR-305 LY033, LY034, LY048	Site Conditions:	Dry

ACTI	ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)													
	Tree Felling			Clearing/Grubbing		Rough Grading		Trenching		Stri	nging/Welding			
	Lowering/Backfilling			Final Grading		Temp. Stabilization	\boxtimes	Perm. Stabilization	n 🗌 Other		er			
									Yes	No	N/A			
	1.	1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?								\boxtimes				
	2.	2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?								\boxtimes				
	3.	Areas of o	ffsite	sediment deposition o	bserve	d?				\boxtimes				
	Comments: Inspected the following resources: S-II2, S-CD1 and W-CD1. Routine Maintenance: (72-Hour Deadline from Notification) - Laydown Yard 034: Remove ECDs that are damaged and no longer needed per MS-18. - Laydown Yard 048: Remove ECDs that are damaged and no longer needed per MS-18. Ineffective Controls: (24-Hour Deadline from Notification) - Laydown Yard 034: Stabilize or adequately protect stockpiles with sediment trapping measures per MS-2. - Laydown Yard 048: Stabilize denuded areas within the LOD.													

Deadline: Various - See Comments

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:

Date: Thursday, September 12, 2024



STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

FIELD INSPECTION PHOTO LOG

Fig. 1 Laydown Yard 034: Remove damaged/controls no longer needed.



Fig. 2 **Laydown Yard 034:** Stabilize or adequately protect stockpiles.



Fig. 3 **Laydown Yard 034:** Stabilize or adequately protect stockpiles.



Fig. 4 **Laydown Yard 048:** Remove damaged/controls no longer needed.





STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

FIELD INSPECTION PHOTO LOG

Fig. 5 **Laydown Yard 048:** Properly stabilize denuded areas.



Fig. 6 **Laydown Yard 048:** Properly stabilize denuded areas.



Fig. 7 **Laydown Yard 048:** Properly stabilize denuded areas.

